

## **Steel Guard Welding Curtains    Weld-View Color Chart**



Transparent Yellow – Lightest, Ideal when dim lighting obstructs work.



Transparent Orange – Medium, blocks most ultra violet radiation.



Transparent Blue – Medium-High, blocks most ultra violet radiation



Transparent Green – Darkest – Provides excellent protection against very bright welding with minimal visibility.